




APS FDR-PRI Power Transformer



**WARNING: Do not ground the Green/Yellow wire if it is not shown on your schematic. This Center tap should be insulated and floated if not being used. Contact Mercury with any questions.*